



Intel® Trusted Execution Engine HW DRM Playback Failure

Technical Advisory

WW41, October 2015

Document Number: 561499

Legal Disclaimer

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Intel technologies may require enabled hardware, specific software, or services activation. Check with your system manufacturer or retailer.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or visit www.intel.com/design/literature.htm.

Intel, the Intel logo, are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

© 2015 Intel Corporation. All rights reserved.

Background

- Cherry Trail and Braswell based SoCs provide HW DRM playback capabilities.
- These capabilities allow end users to consume DRM content via Play Ready 3 which is used by content providers such as Netflix*.

Platform Impact

- Cherry Trail (CHT) – Running Windows* 10
- Braswell (BSW) – Running Windows* 10

Impact

In case HW DRM playback is used (example - Play Ready 3, Netflix*)

- The playback will randomly fail and requires the end user to restart the playback.

Recommendation

Intel recommends that form factor designs that are using HW DRM as mentioned above, should upgrade their Intel® TXE firmware to 2.0.1.2091 or above.

- TXEI Driver Dependencies
 - CHT 2.0.0.1067 or higher
 - BSW 2.0.0.1088 or higher

